

# Control Overview

Most generally, the goal of any controller is to make a machine do what we want it to

Q: What's the simplest controller you can think of?

1) no control  $\rightarrow$  just turn on and go (no correction for errors, etc.)

2) on/off

- thermostats  $\leftarrow$
- air compressors

Pseudo-code for Air Conditioner

```
if (temp > desired temp) {
  turn AC on;
} else {
  turn AC off;
}
```


Q: What are the problems with this?

- no accounting for magnitude of error  $\}$  make control input proportional to error
- doesn't consider rate of change of error  $\}$  make control input prop to  $\frac{d}{dt}(\text{error})$
- can result in rapid switches
- will (almost) always deviate from desired  $\}$  make control input prop to  $\int(\text{error})dt$


PID Feedback Control

Block diagrams: represent the elements of the system as blocks

The input/output relationships of the blocks are shown as lines




# Basic Feedback Control



This always exists, even if not explicitly shown.

$r(t)$  does not have to be  $y_d(t)$

## The "textbook" version



$G_{FB}$ : Feedback controller

acts on  $e(t)$ , the error between reference and current state

$G_P$ : The "plant" - the system to be controlled

Q: What should  $G_{FB}$  be?

proportional to error

Proportional Control


(if I'm far away from where I want to be, a larger corrective action is needed)

## Proportional Control

$$u(t) = k_p e(t) = k_p (x_d(t) - x(t))$$

## Proportional Control Example

$$u(t) = k_p e(t) = k_p (x_d(t) - x(t))$$



$$m\ddot{x} + c\dot{x} + kx = f$$

taking the Laplace Transform


$$(ms^2 + cs + k)X(s) = F(s)$$

$$\frac{X(s)}{F(s)} = \frac{1}{ms^2 + cs + k} \quad \left\{ \text{Transfer function} \right.$$

Let  $m=1\text{kg}$ ,  $k=20\text{N/m}$ ,  $c=10\text{N/m}^2$

Goal: A unit change in position.

Q: What will the response to a unit step in  $f(t)$  look like?



This is the open-loop response

Open-loop - input is not adjusted according to output

Q: Problems with this response?

- steady-state error
- slow rise time

Try proportional control:

$$\text{Let } f(t) = k_p(x_d(t) - x(t)) \rightarrow m\ddot{x} + c\dot{x} + kx = k_p(x_d - x)$$


$$m\ddot{x} + c\dot{x} + (k + k_p)x = k_p x_d$$

$$[ms^2 + cs + (k + k_p)]X(s) = k_p X_d(s)$$

$$\frac{X(s)}{X_d(s)} = \frac{k_p}{ms^2 + cs + (k + k_p)} \quad \left\{ \text{closed-loop transfer function} \right.$$

## Proportional Control Example (cont.)

Try  $k_p = 300$



Q: Better?

- shorter rise time
- less steady-state error

Q: Worse?

- Introduced overshoot
- Introduced oscillation

Q: How can we improve?

- better selection of  $k_p$  (maybe)
- add derivative gain

## Proportional-Derivative Control

$$f(t) = k_p e(t) + k_d \dot{e}(t) = k_p(x_d - x) + k_d(\dot{x}_d - \dot{x})$$


sub. into Eq of Motion:

$$m\ddot{x} + c\dot{x} + kx = k_p(x_d - x) + k_d(\dot{x}_d - \dot{x}) \rightarrow m\ddot{x} + (c + k_d)\dot{x} + (k + k_p)x = k_p x_d + k_d \dot{x}_d$$

Take the Laplace Transform

$$[ms^2 + (c + k_d)s + (k + k_p)]X(s) = [k_d s + k_p]X_d(s) \rightarrow \frac{X(s)}{X_d(s)} = \frac{k_d s + k_p}{ms^2 + (c + k_d)s + (k + k_p)} \quad \left\{ \begin{array}{l} \text{closed-loop} \\ \text{transfer func} \end{array} \right.$$

Let  $k_p = 300$  and  $k_d = 10$



Q: Better?

- less overshoot
- less oscillation  
(better settling time)

Q: Problems?

- still steady-state error
- need to know velocity to implement

not trivial!

Q: How can we eliminate the steady-state error?

Q: Why is there steady-state error?

force generated by the controller not enough to overcome other system forces

For this example




$$m\ddot{x} + c\dot{x} + kx = k_p(x_d - x) + k_d(\dot{x}_d - \dot{x})$$

$$kx = k_p(x_d - x)$$

- at steady-state, all "motion" terms are zero

at  $x_d$ ,  $F_{sp} = kx_d \leftarrow$  Our controller doesn't generate enough force to balance this.

Q: Why not just increase  $k_p$ ?



Q: What other problem is not shown in these plots?

- actuator effort (the force the controller is generating)

- higher peak
- oscillatory

# Proportional-Integral-Derivative (PID) Control

Add an integral controller to remove steady-state error

Q: Integral Control?

"goal" - small errors sum over time to create a large-enough value to induce corrective action

$$f(t) = k_p e + k_d \dot{e} + k_i \left[ \int e(t) dt \right] = k_p (x_d - x) + k_d (\dot{x}_d - \dot{x}) + k_i \left[ \int (x_d - x) dt \right]$$

Sub. into Eq of Motion:

$$m\ddot{x} + c\dot{x} + kx = k_p(x_d - x) + k_d(\dot{x}_d - \dot{x}) + k_i \left[ \int (x_d - x) dt \right]$$


$$m\ddot{x} + (c+k_d)\dot{x} + (k+k_p)x + k_i \int x dt = k_p x_d + k_d \dot{x}_d + k_i \int x_d dt$$

Take the Laplace Transform:

$$\left[ ms^2 + (c+k_d)s + (k+k_p) + \frac{1}{s}k_i \right] X(s) = \left[ k_d s + k_p + \frac{1}{s}k_i \right] X_d(s) \quad \leftarrow \text{multiply by } s$$

$$\left[ ms^3 + (c+k_d)s^2 + (k+k_p)s + k_i \right] X(s) = \left[ k_d s^2 + k_p s + k_i \right] X_d(s)$$

$$\frac{X(s)}{X_d(s)} = \frac{k_d s^2 + k_p s + k_i}{ms^3 + (c+k_d)s^2 + (k+k_p)s + k_i} \quad \left\{ \begin{array}{l} \text{closed loop} \\ \text{transfer function} \end{array} \right.$$



$$k_p = 350$$

$$k_d = 25$$

$$k_i = 300$$

## PID Trends

As this gain is increased  $\rightarrow$  These general trends occur.

Gain	Rise Time	Overshoot	Settling Time	Steady-State Error
$k_p$	$\downarrow$	$\uparrow$	$\approx$	$\downarrow$
$k_d$	$\approx$	$\downarrow$	$\downarrow$	$=$
$k_i$	$\downarrow$	$\uparrow$	$\uparrow$	$\rightarrow 0$

## Questions to Answer & Things to Consider

1) How do we measure the states we need for feedback?

NOT TRIVIAL!!!

2) What about sensor noise?

3) How do we choose the gains ( $k_p, k_d, k_i$ )?

- Optimization
- Heuristic Tuning Methods / algorithms  $\leftarrow$  Ziegler-Nichols Method
- Iterative / Brute Force Methods  $\leftarrow$  "Twiddle"
- Trial-and-Error

4) How do we actually implement?